



FIG. 1




FIG. 2

S11 log MAG 5dB/ REF 0 dB
S21 log MAG 10dB/ REF 0 dB




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

$\begin{matrix} a1 \\ \diagdown \\ a2 \end{matrix}$	x0 [mm]	x1 [mm]	x2 [mm]
y0 [mm]	CHAR·A	CHAR·B	CHAR·C
y1 [mm]	CHAR·D	CHAR·E	CHAR·F
y2 [mm]	CHAR·G	CHAR·H	CHAR·I

CHAR= CHARACTERISTIC VALUES